Approved For Release 2000/06/09: CIA-RDP89B00569R000300050034-7 28 JAN 62 2220Z THOP SECRET E T DOGUMENT NO. NO CHANGE IN CLASS. CHANGE IN CLASS. CHANGE IN CLASS. CHANGE IN TS (S) C DEXT IL. VI. V. V. V. V. AUTH: HR 10-2 DATE: 28 Aug D RAH IN 27564

25X1A 25X1A

25X1A

25X1A°

25X1A

25X1A

25X1A

Marin :

1... 16/14:

1 REF-FERRY TO

TOP: 25 1011 52 22, 52

BRAKER FOR FLAPS POPPED ON ARTICLE -358 DURING FERRY FLIGHT TO

DRIVER-REPORTED CIRCUIT

25X1A

US ON 26 JAN. MAINTENANCE PERSONNEL RAN FLAPS THROUGH
NUMEROUS TIMES MORNING 27 JAN BUT WERE UNABLE TO REPEAT MALFUNCTION
ON THE GROUND. DURING PREFLIGHT PRIOR TO SORTIE FOR SHAKEDOWN
OF SYSTEMS SCHEDULED ON 28 JAN FLAP MALFUNCTION REOCCURED.
THE CIRCUIT BRAKER POPPED AND FLAPS WOULD NOT OPERATE IN ANY
SWITCH POSITION.

- 2. A THOROUGH CHECK OF WIRING INDICATES PROBLEM IS IN AN AREA REQUIRING ENGINE ROLL BACK. SUSPECT THAT A WIRE HAS BEEN SHORTED TO GROUND.
- 3. IT WILL BE IMPOSSIBLE TO FLY ARTICLE 358 ON 28 JAN AS
 PLANNED, EXPECT TO CORRECT MALFUNCTION ON 28 JAN AND FLY SHAKEDOWN
 SORTIE ON BOTH 358 AND 343 ON 29 JAN.
- A. WE EXPECT TO BE READY TO DEPART ON FERRY FLIGHT 30/1100Z
 AS PLANNED WITH EITHER 358 OR 343. EVERY EFFORT WILL BE MADE
 TO HAVE ARTICLE 358 READY.

Approved For Release 25000050034-7